DW20

Recessed Door Sensor

Need help? Give us a call. **1-877-826-5443**

Installation

STEP 1

Locate the sensor within 100 ft. of the panel. The environment at the installation site can have significant effect on range.

STEP 2

Avoid mounting the sensor in areas where they will be exposed to moisture or in an area where a temperature range of 32 to 120F cannot be met.

STEP 3

Avoid mounting sensor on metal or in an area with large quantities of metal or electrical wiring as this can cause signaling issues for the sensor.

STEP 4

Use a pencil to mark the location for the sensor and the magnet.

STEP 5

Using an 11/16" drill bit slowly drill two holes directly across from each other. The sensor diameter is designed to be slightly larger than 11/16" to have a snug fit.

STEP 6

Use the plastic two-hole screw cap to mount the recessed sensor into the door or frame.

STEP 7

Insert the magnet in the hole across from the sensor.



