

Glass Break Detector

Need help? Give us a call.
1-877-826-5443

Installation

STEP 1

Locate the sensor within 100 ft. of the panel. The environment at the installation site can have significant effect on range.

STEP 2

Avoid mounting the sensor in areas where they will be exposed to moisture or in an area where a temperature range of 32 to 120F cannot be met.

STEP 3

Avoid mounting sensor on metal or in an area with large quantities of metal or electrical wiring as this can cause signaling issues for the sensor.

STEP 4

Place the Glass Break Sensor within 15 feet of the window being protected.

STEP 5

Hold detector upside down and twist base counterclockwise to remove from back plate. Install batteries. Wait 5 seconds for power-up delay.

STEP 6

Place the glass break back plate on the opposite wall, adjacent wall, or on the ceiling.

STEP 7

Affix the base to the desired location using the 3 long mounting screws with supplied anchors.

STEP 8

Attach the detector to the base by matching the alignment marks and twisting clockwise.

